



PO Box 2590, 420A 4th Street NE
Salmon Arm, BC, V1E 4R5
Phone 250.832.8380

July 11th, 2018

Columbia Shuswap Regional District
555 Harbourfront Drive NE
Salmon Arm, BC
V1E 3M1

RE: Letter Regarding Hall Renovations

To whom this may concern,

This letter is in regard to the current status of the Blind Bay Memorial Hall based on the recently observed ground saturation and flooding onsite.

Currently, the upper South-West area of the property is fully saturated due to ground water flows from above. This is causing flooding in the basement of the hall via groundwater flows. It is our professional opinion that due to this recurring flooding, the hall is unable to undertake any renovations required to remediate the damage. The Hall will need to install the proposed drainage system to stop the hall from further flooding's and water damage.

If you have any questions, please send inquiries to mike@franklinengineering.ca.

Prepared by,

A handwritten signature in blue ink, appearing to read 'Mike Casol'.

Mike Casol, EIT

Reviewed by,

A handwritten signature in blue ink, appearing to read 'Jayme Franklin', is written over a circular professional seal. The seal contains the text 'PROFESSIONAL ENGINEER', 'BRITISH COLUMBIA', and the number '#34134'.

Jayme Franklin, P.Eng.



PO Box 2590, 420A 4th Street NE
Salmon Arm, BC, V1E 4R5
Phone 250.832.8380

July 11th, 2018

Columbia Shuswap Regional District
555 Harbourfront Drive NE
Salmon Arm, BC
V1E 3M1

RE: CSRD's Onsite Wastewater System at the Blind Bay Memorial Hall

To whom this may concern,

This letter is regarding the current state of the CSRD's Wastewater Disposal Area on the Blind Bay Memorial Hall property. The disposal area has been severely compromised from water flowing from the areas above the field. There is standing water on top of the disposal area and pump cycling was observed via small water geysers out of the ground when the pumps were in operation.

Currently, the whole upper South-West area of the property is fully saturated due to water flowing from above. It is our professional opinion that the disposal area is not in a functioning state and should not be used until system remediation by an Authorized Professional or Registered Onsite Wastewater Practitioner has deemed it suitable for use via a Compliance Inspection Report.

It also appears that the Disposal Area is not within the Registered Easement. Further investigation is recommended.

If you have any questions, please send inquiries to mike@franklinengineering.ca.

Prepared by,

A handwritten signature in blue ink, appearing to read 'Mike Casol'.

Mike Casol, EIT

Reviewed by,

A handwritten signature in blue ink, appearing to read 'Jayme Franklin', is written over a circular professional seal. The seal contains the text 'PROFESSIONAL ENGINEER', 'J. FRANKLIN', and '# 34134'.

Jayme Franklin, P.Eng.